



Siemens&SIPLACE&Asm ins tock September 2020

S/NO	ITEM	DESCRIPTION	QTY'
R1	03048858-01 wpcd 00306736-01		13
R2	03060695 Splice sensor B3+ X8-X12		8
R3	30pcs 03038133 Splice sensor S5		86
R4	( 03082687@03059623@03096377@03170613 )	FCU	16
R5	GCU ( 03052200 )		23
R6	MGCU ( 03103477 )		61
R7	MGCU2-03117531		2
R8	MHCU ( 03109668 )		9
R9	S50 ( 00331581 )		16
R10	Y ( 03094995/03094996/03047216 )		19
R11	( 03058627/03102532/03113016/03050314 )	DPM OTOR	83
R12	MOTOR03058631		38
R13	( 03058802/03072785/03055438/03106620 )		23
R14	3081381		45
R15	D ( 03042306 )		81
R17	CABLE 03062798/03062799/03073100 )		196
R18	BE SENSOR ( 03083001/03037106/03092400 )		2
R19	03028359/03038725/03065425S06		2
R20	X 03077941		2
R21	00372614/00354922/03078122 )		2
R22	MTC 00372607		2
R23	00359418 )		8
R24	( 03016831/03066107&03065782/03101503 )	CP20A/CP/CP20P	3
R25	CPP/DP03039099 )		26
R26	SCS ( 03054790 )		2
R27	03115167 ( 00353450/00353447/00353449 )		9
R28	3020101		2
R29	00359505D		2
R30	POWER SUPPLY ( 03048511/56001072 )		7
R31	56001227/56001191/56001629		2
R32	HS50,00335214		12
R33	03088241 MOTOR		32
R34	3034148		5